



CAR WAY CO., LTD.

1F., NO. 8, ALLEY 10, LANE 20, WAN AN STREET
 BANCIAO DIST., NEW TAIPEI CITY, TAIWAN R.O.C.
 TEL: 886-2-2963-6702 FAX: 886-2-2963-1897

WEBSITE: <http://www.carwayparts.com>

EMAIL: auto@carwayparts.com

Crankshaft Position Sensors

FOR LAND ROVER

| | | | |
|---|---|--|--|
|  |  |  | |
| <p>CW-CPS-0113 OEM: ERR6119</p> <p>RANGE ROVER P38 V8 1996-1997 LAND ROVER DEFENDER 4.0 V8 DISCOVERY S1 4.0 V8</p> | <p>CW-CPS-0113 OEM: NSC100790</p> <p>DEFENDER TD5 DIESEL DISCOVERY II TD5 '98-04</p> | <p>CW-CPS-0114 OEM: ERR6357</p> <p>DISCOVERY I V8 RANGE ROVER P38A V8 '97-02</p> | |
| | | | |